


Velikova
DENTAL LAB

PFM Preparation Guide

Preparations for crowns and bridges







Measurements in mm. With conventional cementation, a minimum height of 3 mm of the prepared stump and a convergence angle of approx. 6° must be observed.

Observe a minimum connector area of 9 mm² for bridges. The connector diameter depends on the alloy in use (see range of alloys).